

NEW HEADQUARTERS BUILDING  
Construction Progress Report  
18 February 1963

Main Building

STATINTL

STATINTL Building Access for [ ] The "SERVICE" badges which  
STATINTL previously allowed [ ] unescorted access were rescinded 1 February.  
STATINTL Since then visits by [ ] to investigate air conditioning  
problems and follow-up punch list items have been severely curtailed because  
it is impractical to escort them around the building. The Office of Security will  
expedite their clearance for no-escort access, but it will require a minimum  
of 30 days. Their personal history statements are now being submitted.

C  
O  
P  
Y

TRANSMITTAL SLIP		DATE <i>11. 14 63</i>
TO: <i>Colonel Edwards</i>		<i>18</i> MAY 1963
ROOM NO.	BUILDING	
REMARKS:  <i>The problem raised by Col. White has been taken care of.</i>		
FROM:	<div style="border: 1px solid black; width: 200px; height: 30px;"></div>	
ROOM NO.	BUILDING	EXTENSION

FORM NO. 241  
1 FEB 55

REPLACES FORM 36-8  
WHICH MAY BE USED.

GPO : 1957—O-439445 (47)

STATINTL